General Environmental Incident Summary

Incident: 4144 Date/Time Notice: 6/25/2016 0950 DEM Incident No:

Responsible Party: Oneok Rockies Midstream

Date Incident:6/24/2016Time Incident:2200Duration:County:McKenzieTwp:148Rng:105Sec:36Qtr:Lat:47.59130Long:-103.99640Method:Interpolation from map

Location Description: Grasslands Plant

16001 Bennie Peer Road Sidney, MT 59270

Submitted By: Levi Weltikol Affiliation:

Address: 896 25th St SE

City: Sidney State: MT Zip: 59270

Received By:

Contact Person: Levi Weltikol

896 25th St SE Sidney, MT 59270

Distance Nearest Occupied Building: Release Contained: Yes

Type of Incident: Pump Leak

Description of Released Contaminant: #2 Diesel Fuel

Volume Spilled: 100.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident: Equipment failure

Risk Evaluation:No immediate risk

of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

No Environmental Impacts

Action Taken or Planned:

Isolated pump. soil to be removed.

Wastes Disposal Location: certified landfill

Agencies Involved:

Updates

Date: 6/25/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 7/12/2016 Status: Inspection Author: Cooper, Mike

Updated Volume:

Notes:

Arrived on site at 4:30 p.m. 61 degrees, wind 15-20 mph. Talked with site contact (Levi Weltikol) . I was told that the site has been cleaned up and the material disposed of. However, I was unable to get access to plant as an escort was unavailable at the time. Levi will be sending me photos via e-mail to confirm contamination and cleanup has been completed. Spill happened within plant boundary.

Date: 7/19/2016 Status: Correspondence Author: Cooper, Mike

Updated Volume:

Notes:

Received pictures from Levi Weltikol. Pictures will be put into file folder.